

WORK ORDER REQUEST

6 September 1957  
Request #9-6-3

SUBJECT: Request for Repair (Contract [REDACTED])

STATINTL

TO: [REDACTED]

STATINTL

FROM: [REDACTED]

Request the following item be repaired and returned to this activity at the earliest possible date:

1. BA-ER44-1 Ser No. 58 each 1
2. BA-CR44-366 each 1 (Serviceable container)

Further request that return shipping documents reflect above work order request number.

NOTE: Installation personnel included following information on shipping document for above item: "Sextant damaged internally, heading and azimuth controls are inoperative. Filter control is rough, light broken."

STATINTL

AUTHORIZED BY: [REDACTED]